

EXHIBIT A

Speights & Runyan
100 Pine Street
Photograph Log
January 6-7, 1999

Photo Number	Sample Number	Photograph Location and Description
6 19:19	NA	3 rd floor, view of Retro-Guard® respray
6 19:25	NA	3 rd floor, view of abated steel and deck
6 19:27	NA	3 rd floor, view of abated column
6 19:28	NA	3 rd floor, view of flutes in deck
6 19:30	NA	3 rd floor, view of wrapped air ducts
6 19:31	NA	3 rd floor, view of beam column interface
6 19:45	NA	25 th floor, Suite 2555, view of central core area below ceiling
6 19:50	NA	25 th floor, Suite 2555, view of fireproofing inside induction unit
6 19:53	NA	25 th floor, Suite 2555, view of Malcolm opening ceiling
6 19:55	NA	25 th floor, Suite 2555, view of inside induction unit
6 20:16a	NA	25 th floor, Suite 2555, view of fireproofing above ceiling tile
6 20:16b	NA	25 th floor, Suite 2555, view of fireproofing above ceiling tile
6 20:17	NA	25 th floor, Suite 2555, view of fireproofing above ceiling tile
6 20:18	Debris 1	25 th floor, Suite 2555, view of fireproofing debris on ceiling tile
6 20:26	Debris 2	25 th floor, Suite 2555, view of fireproofing inside induction unit
6 20:38	NA	25 th floor, telephone closet, view of California asbestos warning sign
6 20:39	Debris 3	25 th floor, telephone closet, debris on Muzak® timer
6 20:46	NA	25 th floor, suite 2525, view of debris on top of ceiling tiles
6 20:47	NA	25 th floor, suite 2525, view of fireproofing on beams and deck
6 20:48	NA	25 th floor, suite 2525, view of debris on top of light fixture
6 21:33*	NA	Suite 1850, view of delamination above ceiling tile
6 21:35	NA	Suite 1850, view of delamination above ceiling tile
6 21:36	NA	Suite 1850, view of debris above ceiling tile
6 21:37	NA	Suite 1850, view of debris above ceiling tile
6 22:27a	NA	Suite 1800, view of fireproofing on deck
6 22:27b	D-01	Suite 1800, view of dust sample location, before sampling
6 22:28	NA	Suite 1800, view above dust sample location
6 22:45	D-01	Suite 1800, view after dust sample
6 23:13	NA	Location not recorded
6 23:14	NA	Location not recorded
6 23:23	D-02	Suite 1700, view of dust location after sampling
7 0:00	NA	Suite 1700, northeast corner, view of fireproofing debris on ceiling tile
7 0:01	NA	Suite 1700, northeast corner, view of fireproofing
7 0:02	NA	Suite 1700, northeast corner, view of fireproofing above fiberglass on ducts
7 18:17	NA	33 rd floor, north most elevator shaft above car #11, view of fireproofing on beam

* Photo did not develop.

NA=Not applicable

**Speights & Runyan
100 Pine Street
Photograph Log
January 6-7, 1999**

Photo Number	Sample Number	Photograph Location and Description
7 18:17b	NA	33 rd floor, north most elevator shaft above car #11, view of fireproofing on beam
7 18:30	NA	19 th floor, low rise shaft, car #6, (northeast corner), view of fireproofing on beam
7 18:31	NA	19 th floor, low rise shaft, car #6, (northeast corner), view of fireproofing on beam
7 18:38	NA	19 th floor, low rise shaft, car #1, (southwest corner), view of fireproofing on column
7 18:51	NA	Bi-level pit of elevator, south side of high rise bank, view of fireproofing debris on pit floor
7 18:52	NA	Bi-level pit of elevator, south side of high rise bank, view of fireproofing debris (different) on pit floor
7 18:53	NA	Bi-level pit of elevator, south side of high rise bank, respirator on metal work of elevator
7 19:03	NA	Floor 22, view of fireproofing on beams in return air shaft
7 19:07	NA	Floor 22, view of fireproofing debris on fiberglass insulation
7 19:09	NA	Floor 22, view up side of insulated supply air duct in return shaft
7 19:20	NA	16 th floor, view of floor walker duct, no longer used
7 19:24	NA	16 th floor, view of new construction in progress
7 19:33a	NA	2 nd floor, low rise air shaft, view of debris on floor
7 19:33b	NA	2 nd floor, low rise air shaft, view of debris on duct
7 19:34	NA	2 nd floor, low rise air shaft, view of air shaft
7 19:35	NA	2 nd floor, view of fireproofing on beam in air shaft



WORKING
COPY

2231 Robinson Road, Suite B
Marietta, Georgia 30068
Telephone: (770) 977-4767
Facsimile: (770) 977-5540

PHOTOGRAPH LOG (1 of

Facility: 100 Pine Street Building: _____
Inspector/Photographer: W. Ewing / T. Dawson Date: 1/6/98
Camera Make/Model: _____ S/N: _____
Film: _____ ASA: _____ Exposures: _____
Processed By: _____ Date Sent: _____ Date Returned: _____

Photo Number	Sample Number	Photograph Description
619:19		3rd Floor, View of Retroguard reentry
✓ 619:25		, View of abated steel + deck
✓ 619:27		, View of abated column
✓ 619:28		, View of flutes in deck
✓ 619:30		, View of wrapped hand air ducts
✓ 619:31		, View of beam column interface
✓ 619:45		Side 25155 25th Floor, View of central core area below ceiling
✓ 619:50		, View of FP inside induction unit
✓ 619:53		, View of Malcolm opening ceiling
✓ 619:55		, View of inside induction unit
✓ 620:18	a-	, View of FP above CT
✓ 20:16		, View of FP above CT
✓ 20:17		, View of FP above CT
✓ 20:18	debris 1	, View of FP debris on CT
✓ 20:26	debris 2	, View of FP inside induction unit
✓ 20:38		25th Fl, ISLOWOW closet, view of asbestos warning sign
✓ 20:39	debris 3	↓ ↓ Debris on Murok area truss
✓ 20:46		25th Fl, Suite 2525, view of debris on top of CTs
✓ 20:47		, View of FP on beams/ded deck
✓ 20:48		, View of debris on top of light fixture

PHOTOGRAPH LOG 2

Photo
Number 21:33

[illegible]

William M. Ewing, CFI
Compass Environmental, Inc.
 2231 Robinson Rd., Suite B
 Marietta, Georgia 30068
 Phone (404) 977-4767
 FAX (404) 977-5540

BULK SAMPLE LOG



Facility: _____




Building: 100 Pine Street




Inspector: W. EWING - T. DAWSON

Date: 1/6/98

[illegible]












STYLE NO. 46-6P

P.O. BOX 607638 • ORLANDO, FL 32860 • (407) 886-3100

File
PRESERVERS









STYLE NO. 46-6P

P.O. BOX 607638 • ORLANDO, FL 32860 • (407) 886-3100

RESERVERS
FILE






84:02 9





STYLE NO. 46-6P




P.O. BOX 607638 • ORLANDO, FL 32860 • (407) 884-3100




File
PRESERVERS





23:14
6








7
0:00

STYLE NO. 46-6P

P.O. BOX 607638 • ORLANDO, FL 32860 • (407) 886-3100

File
PRESERVERS








STYLE NO. 46-6P

P.O. BOX 607638 • ORLANDO, FL 32860 • (407) 886-3100

File
PRESERVERS





STYLE NO. 46-6P

P.O. BOX 607638 • ORLANDO, FL 32860 • (407) 884-3100

File
PRESERVERS

